




Enable Cursor Spectrum View
 External Trigger

Main Chart Color Spectrum

Graph Calibration Dis

HGJ, Absolute Irradiance, P0



Graph Control



Display Options

View

- Raw Data
- Dark
- Reference
- Dark Subtracted
- % T/R
- Absorbance
- Absolute Irradiance

絶対表示を選択



(有)たきぶん

BRC112

Dark: ON Ref.: ON Dark Compensate: OFF P Mode: 0

50 50 1 1